

FEATURES	NOC RUST TECH 3 IN 1 SPRAY, produced from special modified acrylic resin providing excellent adhesion and fast drying . use as a primer and topcoat (3in1) on a variety of metal substrates, structural, galvanized, steel, aluminum. Can be applied over the old paint and offer corrosion resistant and effectively rust preventing with high build smooth film. Can be use for interior and exterior.
TECHNICAL INFORMATION Type Color Film appearance Pack size Flash point Pressure Specific gravity Wet film thickness Dry film thickness Theoretical coverage Touch dry (25-30°C) Recoat dry (25-30°C) Full cure (25-30°C)	Acrylic Lacquer White,Black,Gray and Silver Gloss, Matt 400 cc -10 C° 4 Bar 0.818-0.924 100-125 Microns 10.33-12.91 Microns 1.40 Sq.m./coat/400 cc Remark - Actual Surface coverage will depend on surface irregularities, technique, Application Condition method and dimension of the object to be coated 10-15 Minutes 10-15 Minutes 45-60 Minutes
APPLICATION Application method Condition during application	1. Shake can thoroughly 2 minutes before using and shakes periodically during spray 2. Spray from a distance of about 6-8 inches with opening in spray head pointed towards object. Press level down with index finger, keeping can in motion from side to side so that coating is deposited evenly. 3. Spray several thin coatings with an interval of 10 minutes 4. After spraying turn can upside down and press spray head to clean the spray nozzle It is advisable to finish the whole can once start to use, to avoid the block of dry paint in the valve after use. Use respiratory mask with charcoal and dust filter, gloves, eye wear. No smoking while apply.
APPLICATION SYSTEM Surface Preparation Coating system Primer & Topcoat	Surface must be clean, dry and free from oil, grease and contaminants before painting. For previously painted surfaces, remove all unstable paint film, loose chalk, dust and foreign matter. Substrate sanding is preferable especially on smooth surface. Apply 2-3 coats of N.O.C. GALVANIZED 3IN1 SPRAY.
HANDLING AND STORAGE	Keep the containers in a dry, cool, well ventilated space and away from heat. Keep away from source of heat and ignition. Containers must be kept tightly closed.
HEALTH AND SAFETY	Use under well ventilated conditions. Avoid skin contact.