

<b>FEATURES</b>	<p>HATO Lacquer Primer Surfacer is formulated from Nitro-Cellulose, alkyd resin and premium color pigments. Paint film is fast dry, easy to scrub, high coverage and highly adhesive with many surfaces such as real wood, plywood, MDF board and metal.</p>																														
<b>TECHNICAL INFORMATION</b>	<table> <tr> <td>Type</td> <td>Nitrocellulose</td> </tr> <tr> <td>Color</td> <td>Grey</td> </tr> <tr> <td>Film appearance</td> <td>Matt</td> </tr> <tr> <td>Pack size</td> <td>1/4, 1 and 5 Gallon</td> </tr> <tr> <td>Solid by volume</td> <td>40 ± 2%</td> </tr> <tr> <td>Solid by weight</td> <td>60 ± 2%</td> </tr> <tr> <td>Specific gravity</td> <td>1.22-1.32</td> </tr> <tr> <td>Flash point</td> <td>4 C°</td> </tr> <tr> <td>Wet film thickness</td> <td>75-100 Microns</td> </tr> <tr> <td>Dry film thickness</td> <td>30-40 Microns</td> </tr> <tr> <td>Theoretical coverage</td> <td>45-50 Sq.m./coat/gallon</td> </tr> <tr> <td></td> <td>Remark - Actual Surface coverage will depend on surface irregularities, Mixing, Application Condition method and technique; as well as the structure and dimensions of the object to be coated</td> </tr> <tr> <td>Touch dry (25-30°C)</td> <td>1-5 Minutes</td> </tr> <tr> <td>Recoat dry (25-30°C)</td> <td>25-30 Minutes (minimum)</td> </tr> <tr> <td>Full cure (25-30°C)</td> <td>1 Hours</td> </tr> </table>	Type	Nitrocellulose	Color	Grey	Film appearance	Matt	Pack size	1/4, 1 and 5 Gallon	Solid by volume	40 ± 2%	Solid by weight	60 ± 2%	Specific gravity	1.22-1.32	Flash point	4 C°	Wet film thickness	75-100 Microns	Dry film thickness	30-40 Microns	Theoretical coverage	45-50 Sq.m./coat/gallon		Remark - Actual Surface coverage will depend on surface irregularities, Mixing, Application Condition method and technique; as well as the structure and dimensions of the object to be coated	Touch dry (25-30°C)	1-5 Minutes	Recoat dry (25-30°C)	25-30 Minutes (minimum)	Full cure (25-30°C)	1 Hours
Type	Nitrocellulose																														
Color	Grey																														
Film appearance	Matt																														
Pack size	1/4, 1 and 5 Gallon																														
Solid by volume	40 ± 2%																														
Solid by weight	60 ± 2%																														
Specific gravity	1.22-1.32																														
Flash point	4 C°																														
Wet film thickness	75-100 Microns																														
Dry film thickness	30-40 Microns																														
Theoretical coverage	45-50 Sq.m./coat/gallon																														
	Remark - Actual Surface coverage will depend on surface irregularities, Mixing, Application Condition method and technique; as well as the structure and dimensions of the object to be coated																														
Touch dry (25-30°C)	1-5 Minutes																														
Recoat dry (25-30°C)	25-30 Minutes (minimum)																														
Full cure (25-30°C)	1 Hours																														
<b>APPLICATION</b>	<table> <tr> <td>Tools</td> <td>Brush or Spray gun</td> </tr> <tr> <td>Diluent</td> <td>Thinner</td> </tr> <tr> <td>Dilution (%)</td> <td>Brush 100-150% / Spray gun 100-200 %</td> </tr> </table>	Tools	Brush or Spray gun	Diluent	Thinner	Dilution (%)	Brush 100-150% / Spray gun 100-200 %																								
Tools	Brush or Spray gun																														
Diluent	Thinner																														
Dilution (%)	Brush 100-150% / Spray gun 100-200 %																														
<b>APPLICATION SYSTEM</b>	<table> <tr> <td colspan="2"><b>Surface Preparation</b></td> </tr> <tr> <td>New surface</td> <td> <p>Use sandpaper to sand the wood surface until smooth</p> <p>Fill all wood crack and hole by filler</p> <p>Sand again until the smooth surface is obtained</p> <p>The surfaces must be clean and free of dirt, grease, oil, wax, salt, and other contaminants</p> </td> </tr> <tr> <td>Old surface</td> <td> <p>Chalky surfaces or loose material must be removed by stiff brush</p> <p>The surfaces must be clean and free of dirt, wax, salt, old paint, and other contaminants</p> </td> </tr> <tr> <td colspan="2"><b>Coating system</b></td> </tr> <tr> <td>Primer</td> <td>Apply 1 coat of Hato Primer Surfacer (N8000)</td> </tr> <tr> <td>Topcoat</td> <td>Apply 2-3 coats of Hato Industrial Lacquer</td> </tr> </table>	<b>Surface Preparation</b>		New surface	<p>Use sandpaper to sand the wood surface until smooth</p> <p>Fill all wood crack and hole by filler</p> <p>Sand again until the smooth surface is obtained</p> <p>The surfaces must be clean and free of dirt, grease, oil, wax, salt, and other contaminants</p>	Old surface	<p>Chalky surfaces or loose material must be removed by stiff brush</p> <p>The surfaces must be clean and free of dirt, wax, salt, old paint, and other contaminants</p>	<b>Coating system</b>		Primer	Apply 1 coat of Hato Primer Surfacer (N8000)	Topcoat	Apply 2-3 coats of Hato Industrial Lacquer																		
<b>Surface Preparation</b>																															
New surface	<p>Use sandpaper to sand the wood surface until smooth</p> <p>Fill all wood crack and hole by filler</p> <p>Sand again until the smooth surface is obtained</p> <p>The surfaces must be clean and free of dirt, grease, oil, wax, salt, and other contaminants</p>																														
Old surface	<p>Chalky surfaces or loose material must be removed by stiff brush</p> <p>The surfaces must be clean and free of dirt, wax, salt, old paint, and other contaminants</p>																														
<b>Coating system</b>																															
Primer	Apply 1 coat of Hato Primer Surfacer (N8000)																														
Topcoat	Apply 2-3 coats of Hato Industrial Lacquer																														
<b>HANDLING AND STORAGE</b>	Keep the containers in a dry, cool, well ventilated space and away from heat. Containers must be kept tightly closed.																														
<b>HEALTH AND SAFETY</b>	Use under well ventilated conditions. Avoid skin contact.																														